

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	3060483	Machine Start Code:	1945
Make:	JCB	Model:	540-140		
Fleet Number:	MLP13651	Registration Number:	SC21 LKE		
Hour Clock Working:	Y	Machine Hours:	1788		
Tyre Size:	400/80/24	N/S/F%:	60	O/S/F%:	50
		N/S/R%:	60	O/S/R%:	60
Tracks (Steel/Rubber)	N/A		N/S % -	O/S % -	
Blade:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Track Width:	N/A		
Buckets:	N/A		Bucket Sizes:	N/A	
Roller Drum Width:	N/A		Roller -Water Sprinklers System	N/A	
Skip (Straight/Swivel/Hi-Tip):	N/A		Transmission (Hydrostatic/Gear):	N/A	
AdBlue:	N/A		4th Gear:	Y	
Pallet Forks	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Fork Positioners	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Stabilisers:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Gross Weight(kg):	11370	Lift Capacity (kg):	4000	Lift Height (m):	14
Engine (kw/hp) :	55	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Air Conditioning:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Controls (Lever/Joystick):	LEVER		Condition of Cab & Dash Decals	OK	
Hitch (Manual/Hydraulic):	N/A		Reversing Camera	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Body Work Condition (Any Damage):					
Glass (Any Damage):	NO		Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Road Lights:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Paintwork:	OK				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Date & Hours of Last Service:	1579HRS		Date Next Service Due:	2079HRS	
Last Service Sheet Attached:	<input type="checkbox"/> YES <input type="checkbox"/> NO		Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BEEN SENT					
Service Records Supplied:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Red Key with Machine with picture:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Depot:	810				
Inspected By:	J.DENNIBG	Date:	25.08.23		

Record of Inspection
Record of Service



Morris Leslie

PLANT HIRE

Date	Machine	Fitters Time	Workshop Job No			Fleet No	Hours
10.11.22	14m Telehandler					13651	1579H
ENGINE		CHG	CHKD	N/A	Comments & Work Done		
Engine Oil & Filters		X			AT -37		
Air & Fuel Filters/Pre Filters		X					
Coolant Radiator Hoses Antifreeze		X	/				
Fan & Drive Belts & Pulleys			/				
Engine & Other Mountings			/				
Fuel Tank & System		X	/		Change trans oil + filter		
TRANSMISSIONS		CHG	CHKD	N/A			
Operation of Clutch			/				
Transmission Oils & Filters		X	/				
Axle Oils and Breathers			/				
Drive / Prop Shafts & Couplings			/		OK's filled tyres.		
Oil Cooler & Hoses			/				
Wheel Bearing & Hubs			/				
Wheel Nut Tightness, Tyres Cond & Pressures			/		JCB boom pipes fill with 36 litre hgd oil		
HYDRAULICS		CHG	CHKD	N/A			
Hydraulic Oil & Filters Breather Vents		X	/				
Hydraulic Pumps, Pipes & Hoses			/				
Hydraulic Rams, Pins & Bushes			/				
Other Hydraulic Components			/		Straighten boom sensor plate		
EXCAVATORS		CHG	CHKD	N/A			
Track Condition Tension				N/A			
Sprockets, Idlers, Rollers				N/A			
Quick Hitch & Attachments				N/A			
Condition of Boom Dipper/Quick Hitch Sticker				N/A	Grease.		
ROLLERS		CHG	CHKD	N/A			
Roller Mountings				N/A			
Sprinkler Scrapers				N/A	2x rear side light bulb		
TELEHANDLERS/FORKLIFTS				N/A			
Forks Masts Chains & Rollers & Wear Pads			/				
Counter Weight Security & SWL Charts			/				
CABS & CHASSIS		CHG	CHKD	N/A			
Op of Steering & Linkage			/		Bonnet slight crack off New Rear fish eye mirror.		
Op of Foot/Hand & Overrun Brakes			/				
Tow Bar Eye Pin & Retainer			/				
Grease All Points			/				
ELECTRICAL		CHG	CHKD	N/A			
Battery Security & Top Up & Charging Rate			/		Reset Service light & cab filters.		
Lights/Ind/Horn/Beacon/Bleepers/Warn Devices			/				
Engine Gauges & Warning Lights			/				
SAFETY		CHG	CHKD	N/A			
Cab Doors/Steps/Glass/Canopy/Bonnet/Catches			/				
Driver Seat Restraints & Controls & ROPS & FOPS			/		25/6/2023.		
Safety Stickers Warning Signs Etc in Place			/				
ALL FUNCTIONS TEST							
Operations Manual/ML Instructions/Regeneration Stickers			/				
Key			/				
Service Sticker			/		Date: 10/11/22.		
Cleaned			/				
Fleet Number Visible			/				
Glass/Mirrors			/				
Grease Gun			/				

Statutory Inspection Expiry Date: 25/6/2023.

I HEREBY DECLARE that the equipment above was inspected/serviced in accord with the appropriate provisions and found free from any defect likely to effect safety (other than any listed above) and that these details are correct.

Signature: *[Handwritten Signature]* Print: *D. Hood*
 Completed By: *[Handwritten Signature]* Authenticated By: *[Handwritten Signature]*

1 conv customer 1 conv contract 1 conv machine file

Record of Inspection

Record of Service

Morris Leslie

PLANT HIRE

Date	Machine	Fitters Time	Workshop Job No	Fleet No	Hours
11/5/22	JCB 540-140			1365i	942
ENGINE		CHG	CHKD	N/A	Comments & Work Done Full 1000hr service with every filter, 13.5L eng oil
Engine Oil & Filters					
Air & Fuel Filters/Pre Filters					
Coolant Radiator Hoses Antifreeze					
Fan & Drive Belts & Pulleys					
Engine & Other Mountings					
Fuel Tank & System					
TRANSMISSIONS		CHG	CHKD	N/A	11L transfluid
Operation of Clutch				✓	
Transmission Oils & Filters			✓		
Axle Oils and Breathers			✓		
Drive / Prop Shafts & Couplings			✓		
Oil Cooler & Hoses			✓		
Wheel Bearing & Hubs			✓		
Wheel Nut Tightness, Tyres Cond & Pressures			✓		
HYDRAULICS		CHG	CHKD	N/A	
Hydraulic Oil & Filters Breather Vents			✓		
Hydraulic Pumps, Pipes & Hoses			✓		
Hydraulic Rams, Pins & Bushes			✓		
Other Hydraulic Components			✓		
EXCAVATORS		CHG	CHKD	N/A	
Track Condition Tension				✓	
Sprockets, Idlers, Rollers				✓	
Quick Hitch & Attachments				✓	
Condition of Boom Dipper/Quick Hitch Sticker				✓	
ROLLERS		CHG	CHKD	N/A	
Roller Mountings				✓	
Sprinkler Scrapers				✓	
TELEHANDLERS/FORKLIFTS					
Forks Masts Chains & Rollers & Wear Pads				✓	
Counter Weight Security & SWL Charts				✓	
CABS & CHASSIS		CHG	CHKD	N/A	Greased
Op of Steering & Linkage				✓	
Op of Foot/Hand & Overrun Brakes				✓	
Tow Bar Eye Pin & Retainer				✓	
Grease All Points				✓	
ELECTRICAL		CHG	CHKD	N/A	
Battery Security & Top Up & Charging Rate				✓	
Lights/Ind/Horn/Beacon/Bleepers/Warn Devices				✓	
Engine Gauges & Warning Lights				✓	
SAFETY		CHG	CHKD	N/A	
Cab Doors/Steps/Glass/Canopy/Bonnet/Catches				✓	
Driver Seat Restraints & Controls & ROPS & FOPS				✓	
Safety Stickers Warning Signs Etc in Place				✓	
ALL FUNCTIONS TEST					
Operations Manual/ML Instructions/Regeneration Stickers				✓	
Key				✓	
Service Sticker				✓	
Cleaned				✓	
Fleet Number Visible				✓	
Glass/Mirrors				✓	
Grease Gun				✓	

Statutory Inspection Expiry Date:

I HEREBY DECLARE that the equipment above was Inspected/Serviceed in accord with the appropriate provisions and found free from any defect likely to effect safety (other than any listed above) and that these details are correct.

Signature: *Harvey Scothern*

Print: HARVEY SCOTHERN

Completed By:

Authenticated By:

Date: 11/5/22



Development Member



GA1 Fleet Number:

MLP13651

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 and Power Regulations 1998

Date of Thorough Examination: 13/06/2023		Date of Report: 13/06/2023		Report number: ML12M23001220	
Name and Address of employer for whom the thorough examination was made: Morris Leslie, Errol Airfield, Errol, Perth, PH2 7TB			Address of premises at which the examination was made: McDonalds Junction One Retail Park Bidston Moss Leasowe CH44 2HE		
Description and identification of the equipment: Equipment Type: JCB 540-140 Telehandler (SC21 LKE) ID: JCB5A8MGLM3060483 Quick Hitch Type: N/A Quick Hitch S/N: N/A		Safe Working Load(s): In Accordance with manufacture specification found in cab.	Date of manufacture if known: N/A	Date of last thorough examination: N/A	
Is this the first examination after installation or assembly at a new site or location?		Was the examination carried out:			
<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> X		Within an interval of 6 months?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> X	
		Within an interval of 12 months?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> X	
If the answer to the above question is YES has the equipment been installed correctly?		In accordance with an examination scheme?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> X	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> X <input type="checkbox"/> NO <input type="checkbox"/>		After the occurrence of exceptional circumstances?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> X	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) None Found.					
Is the above an existing or imminent danger to persons *Note- This is a reportable defect				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> X	
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) N/A			YES by:		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: Equipment was found to be in safe working order at time of inspection.					
Particulars of any tests carried out as part of the examination: (If none state NONE) None					
Observations / additional comments relative to this thorough examination: Equipment was found to be in safe working order at time of inspection.					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> X <input type="checkbox"/> NO <input type="checkbox"/>	
Name & Qualifications of person making this report: James Walsh City & Guilds, CITB		Name of person signing or authenticating this report on behalf of the author: <i>Mr James Walsh</i> Signature:		Latest date by which next thorough examination must be carried out: 12/06/2024	
Name and address of employer of persons making and authenticating this report: Walsh Plant Ltd, Unit 3 Birchwood Industrial Estate, Hoe Lane, Nazeing, EN9 2RJ					