

Morris Leslie

JOB CARD

PLANT SALES

FLEET NO:	14650	DEPOT NO:	803	WORKSHOP JOB NO:	
-----------	-------	-----------	-----	------------------	--

ENGINEERS NAME:	RICHIE	SITE ADDRESS: BEDFORD.
DATE:	7-10-24.	
MACHINE:	KUBOTA KX027-4	
HOURS:	789	

JOB DESCRIPTION: JOBS / PARTS FITTED.

WORK CARRIED OUT:
CORRECTED LEVELS.

PARTS USED DESCRIPTION	QTY	PRODUCT CODE	PRICE	TOTAL
12V SOCKET	1			
RECTANGLE AIR VENT.	1			
CAB DOOR MECH COVER	1			

LABOUR TIME: 1/2.	SUB TOTAL	
	VAT	
	TOTAL	£

ENGINEER SIGNATURE: R. Loughlin
DATE: 7-10-24.
NAME: R. LOUGHLIN.
W/S SUP:

Morris Leslie

PLANT SALES

Morris Leslie Excavator Inspection Form

ALL BOXES MUST BE COMPLETE FOR ALL MACHINES

MACHINE DETAILS			
Internal stock No:	MLP14650		
Manufacturer:	KUBOTA		
Model:	KXO27-4		
Year:	2022		
Hours:	790		
Serial Number:	57482		
Registration Number:			
Machine Start Code:	RED KEY		
Condition:	<input checked="" type="checkbox"/> Used	<input type="checkbox"/> Ex Demo	
Location Name & Postcode:	BEDFORD MK452FN		
ENGINE			
Engine Manufacturer:	KUBOTA		
Engine Model:	V1505		
Engine Serial Number:	1MU0440		
Engine Output:	17.5 KW		
Emission Level:	<input type="checkbox"/> Stage III B / Tier IV interim	<input type="checkbox"/> Stage IV / Tier IV final	<input type="checkbox"/> Stage V / Tier IV final <input type="checkbox"/> Stage V / Tier V
Eco Mode:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
OTHER INFORMATION			
Gross Weight:	8425	KG	
CE Marked:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Cabin Type:	<input checked="" type="checkbox"/> Open Cabin	<input type="checkbox"/> Enclosed Cabin	
Operator Controls:	<input checked="" type="checkbox"/> Lever	<input checked="" type="checkbox"/> Joystick	
Air conditioning:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Heater:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Heated Seat:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
AD blue:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Attachments:	No. of Buckets	4	
Quick Hitch:	<input checked="" type="checkbox"/> Hydraulic	<input type="checkbox"/> Manual	
Arm Length:	1300	mm	
Reach Type:	<input type="checkbox"/> Standard	<input checked="" type="checkbox"/> Long	
Tail Swing Configuration:	<input checked="" type="checkbox"/> Zero	<input type="checkbox"/> Reduced	<input type="checkbox"/> Conventional
Boom Type:	<input type="checkbox"/> 1-Piece	<input checked="" type="checkbox"/> 2-Piece	
Auxiliary Hydraulics:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Telematics:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Camera:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Rotating beacon:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Green beacon:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Paintwork:			Good general wear and tear
CHASSIS			
Long Undercarriage:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Track Type:	<input checked="" type="checkbox"/> Rubber	<input type="checkbox"/> Steel	
Track % Remaining:	80 <input checked="" type="checkbox"/> N / S	80 <input checked="" type="checkbox"/> O / S	
Track Shoe Width:	300	mm	
Bolt-On Pads:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Undercarriage Type:	<input checked="" type="checkbox"/> Fixed	<input type="checkbox"/> Variable	
Undercarriage % Remaining:	%		
EXTERIOR			
Cab Guards:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Exterior Lighting:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
SELLER'S CONDITION REPORT			
Latest inspection:	24.09.2024	Shipping Length:	4370
Condition Info:	OK	Shipping Width:	1400
Full service history:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Shipping Height:	2420
Certificates:	<input type="checkbox"/> CE Cert <input checked="" type="checkbox"/> Loler Cert	Shipping Weight:	2665
Inspected by:	DAVE		
Date:	11.10.2024		

Please complete and email to: sales.info@morrisleslie.co.uk



Development Member



GA1 Fleet Number:

MLP14650

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 and Power Regulations 1998

Table with 4 columns: Date of Thorough Examination, Date of Report, Report number, Name and Address of employer, Address of premises, Description and identification of the equipment, Safe Working Load(s), Date of manufacture, Date of last thorough examination.

Table with 2 main columns: Is this the first examination after installation... and Was the examination carried out... with sub-tables for YES/NO and X marks.

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) None Found.

Is the above an existing or imminent danger to persons *Note-This is a reportable defect YES NO X

Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) N/A YES by:

Particulars of any repair, renewal or alteration required to remedy the defect identified above: Equipment was found to be in safe working order at time of inspection.

Particulars of any tests carried out as part of the examination: (If none state NONE) None

Observations / additional comments relative to this thorough examination: Equipment was found to be in safe working order at time of inspection.

IS THIS EQUIPMENT SAFE TO OPERATE? YES X NO

Name & Qualifications of person making this report: James Walsh City & Guilds, CITB Name of person signing or authenticating this report on behalf of the author: Signature: Latest date by which next thorough examination must be carried out: 20/12/2024

Name and address of employer of persons making and authenticating this report: Walsh Plant Ltd, Unit 3 Birchwood Industrial Estate, Hoe Lane, Nazeing, EN9 2RJ

