

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	PS04013509	Machine Start Code:	
Make:	KOBELCO	Model:	SK55SRX-6E		
Fleet Number:	SEL29542	Registration Number:	N/A		
Hour Clock Working:	Y	Machine Hours:	1387		
Tyre Size:		N/S/F%:		N/S/R%:	O/S/R%:
Tracks (Steel/Rubber)	Steel	N/S % -	20%	O/S % -	20%
Blade:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Track Width:	n/a		
Buckets:	y	Bucket Sizes:	Ditching, 1ft, 3ft		
Roller Drum Width:		Roller -Water Sprinklers System			
Skip (Straight/Swivel/Hi-Tip):		Transmission (Hydrostatic/Gear):			
AdBlue:		4th Gear:			
Pallet Forks	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Fork Positioners	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Stabilisers:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Gross Weight(kg):		Lift Capacity (kg):	n/a	Lift Height (m):	n/a
Engine (kw/hp) :		Turbo:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Air Conditioning:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Controls (Lever/Joystick):	lever & joystick	Condition of Cab & Dash Decals	GOOD		
Hitch (Manual/Hydraulic):	hydraulic	Reversing Camera	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Body Work Condition (Any Damage):	minor dents & scratches on body work				
Glass (Any Damage):	n/a	Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Road Lights:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Paintwork:	genereal wear & tear throughout				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Date & Hours of Last Service:	n/a	Date Next Service Due:	n/a		
Last Service Sheet Attached:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT					
Service Records Supplied:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Red Key with Machine with picture:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Depot:	810				
Inspected By:		Date:	14.08.23		