

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2016	Serial Number:	Z060345	Machine Start Code:	CODED KEY
Make:	KUBOTA	Model:	KX015-4		
Fleet Number:	HHC60345	Registration Number:	N/A		
Hour Clock Working:	YES	Machine Hours:	2193		
Tyre Size:	N/A	N/S/F%:		N/S/R%:	O/S/R%:
Tracks (Steel/Rubber)	RUBBER	N/S % -	40%	O/S % -	40%
Blade:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Track Width:	N/A		
Buckets:	YES	Bucket Sizes:	DITCH / 12" / 24"		
Roller Drum Width:		Roller -Water Sprinklers System			
Skip (Straight/Swivel/Hi-Tip):		Transmission (Hydrostatic/Gear):	N/A		
AdBlue:	NO	4th Gear:	N/A		
Pallet Forks	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Fork Positioners	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Stabilisers:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Gross Weight(kg):	1495	Lift Capacity (kg):	N/A	Lift Height (m):	N/A
Engine (kw/hp) :	9.6	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Air Conditioning:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Controls (Lever/Joystick):	JOYSTICKS	Condition of Cab & Dash Decals	GOOD		
Hitch (Manual/Hydraulic):	MANUAL	Reversing Camera	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Body Work Condition (Any Damage):	AVERAGE				
Glass (Any Damage):	N/A	Mirrors:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Road Lights:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Paintwork:	AVERAGE				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Green Seat Belt Beacon:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Date & Hours of Last Service:	N/A	Date Next Service Due:	N/A		
Last Service Sheet Attached:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT					
Service Records Supplied:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Red Key with Machine with picture:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Depot:	803				
Inspected By:	ADRIAN MAER	Date:	17.08.23		