

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	3060274	Machine Start Code:	1945
Make:	JCB	Model:	540-140		
Fleet Number:	MLP13645	Registration Number:	SH21 YXB		
Hour Clock Working:	YES	Machine Hours:	2834		
Tyre Size:	400/80/24	N/S/F%:	80%	O/S/F%:	80%
		N/S/R%:	80%	O/S/R%:	60%
Tracks (Steel/Rubber)	N/S % -		O/S % -		
Blade:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Track Width:			
Buckets:	Bucket Sizes:				
Roller Drum Width:	Roller -Water Sprinklers System				
Skip (Straight/Swivel/Hi-Tip):	Transmission (Hydrostatic/Gear):		GEAR		
AdBlue:	4th Gear:		YES		
Pallet Forks	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Fork Positioners	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Stabilisers:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Gross Weight(kg):	11370	Lift Capacity (kg):	4000	Lift Height (m):	14
Engine (kw/hp) :	55	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Air Conditioning:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Controls (Lever/Joystick):	LEVERS		Condition of Cab & Dash Decals	GOOD	
Hitch (Manual/Hydraulic):	Reversing Camera		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Body Work Condition (Any Damage):	GOOD				
Glass (Any Damage):	GOOD		Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Road Lights:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Paintwork:	GOOD				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Date & Hours of Last Service:	N/A		Date Next Service Due:	3000 HR	
Last Service Sheet Attached:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT					
Service Records Supplied:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Red Key with Machine with picture:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Depot:	803				
Inspected By:	ADRIAN MAER	Date:	21.08.23		