

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	216832	Machine Start Code:	2940
Make:	VOLVO	Model:	ECR88D		
Fleet Number:	MLP13487	Registration Number:	N/A		
Hour Clock Working:	Y	Machine Hours:	1922		
Tyre Size:	N/S/F%:	O/S/F%:	N/S/R%:	O/S/R%:	
Tracks (Steel/Rubber)	RUBBER	N/S % -	70%	O/S % -	70%
Blade:	<input type="checkbox"/> YES <input type="checkbox"/> NO	Track Width:	450MM		
Buckets:	3	Bucket Sizes:	DITCH, 24", 12"		
Roller Drum Width:	N/A	Roller -Water Sprinklers System	N/A		
Skip (Straight/Swivel/Hi-Tip):	N/A	Transmission (Hydrostatic/Gear):	N/A		
AdBlue:	N/A	4th Gear:	N/A		
Pallet Forks	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Fork Positioners	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Stabilisers:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Gross Weight(kg):	8752	Lift Capacity (kg):	N/A		
Engine (kw/hp) :	42.4	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Lift Height (m):	N/A
Controls (Lever/Joystick):	N/A	Condition of Cab & Dash Decals	OK		
Hitch (Manual/Hydraulic):	HYD	Reversing Camera	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Body Work Condition (Any Damage):					
Glass (Any Damage):	NO	Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Road Lights:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Paintwork:	OK				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Date & Hours of Last Service:	1921HRS 17/08/2023		Date Next Service Due:	2421HRS	
Last Service Sheet Attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT					
Service Records Supplied:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Red Key with Machine with picture:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Depot:	810				
Inspected By:	J.DENNING	Date:	25.08.23		