

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	3060049	Machine Start Code:	1945
Make:	JCB	Model:	540-140		
Fleet Number:	MLP13633	Registration Number:	SH21 YWM		
Hour Clock Working:	Y	Machine Hours:	1504		
Tyre Size:	400/80/24	N/S/F%:	30	O/S/F%:	30
		N/S/R%:	45	O/S/R%:	40
Tracks (Steel/Rubber)	N/A		N/S % -	O/S % -	
Blade:	<input type="checkbox"/> YES <input type="checkbox"/> NO	Track Width:	N/A		
Buckets:	N/A		Bucket Sizes:	N/A	
Roller Drum Width:	N/A		Roller -Water Sprinklers System	N/A	
Skip (Straight/Swivel/Hi-Tip):	N/A		Transmission (Hydrostatic/Gear):	GEAR	
AdBlue:	N/A		4th Gear:	Y	
Pallet Forks	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Fork Positioners	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Stabilisers:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Gross Weight(kg):	11370	Lift Capacity (kg):	4000	Lift Height (m):	14
Engine (kw/hp) :	55	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Air Conditioning:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Controls (Lever/Joystick):	LEVER		Condition of Cab & Dash Decals	OK	
Hitch (Manual/Hydraulic):	N/A		Reversing Camera	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Body Work Condition (Any Damage):					
Glass (Any Damage):	NO		Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Road Lights:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Paintwork:	OK				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Date & Hours of Last Service:	1146HRS		Date Next Service Due:	1646HRS	
Last Service Sheet Attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BEEN SENT					
Service Records Supplied:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Red Key with Machine with picture:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Depot:	810				
Inspected By:	J.DENNING	Date:	15.09.23		

Morris Leslie

PLANT HIRE

SERVICE REPORT

(Use for On-Site Service, Breakdowns, Damage and Repairs)

DEPOT No.

Saltash

SR

52486

Customer Information			Site Address		
Address <i>Taylor Wimpey</i>			<i>Sherford site Plymouth</i>		
POST CODE		Inv. No.	POST CODE		Contact:-
Acc. No.					
Date Reported	Time	Type of Equipment	Plant I/D No.	Contract No.	Chargeable?
<i>16.6.22</i>		<i>14M JCB</i>	<i>13633</i>		
TYPE>	On Site Service	<input checked="" type="checkbox"/>	Breakdown	Repair / Dam	Other

Reported Fault

machine is due a service

Reported to:-

Passed to:-

Time:-

Engineers Report and Work carried out:-

*To site carry out a 1000 Hk
service machine Hours 1146*

Parts

Parts Used Description	Qty	Product Code	Price Each	Total
Travel Time <i>1</i>	Labour Time <i>3</i>		Sub Total	
			VAT	
			TOTAL	£

Customers Comments:-

Customers Authorised
Signatory
NAME (Block Caps)

Engineers/Fitters Signature

DATE:- *16.6.22*

NAME:-

w/s Sup *A. Wallis*



Development Member



GA1 Fleet Number:

MLP13633

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 and Power Regulations 1998

Date of Thorough Examination: 16/05/2023		Date of Report: 16/05/2023		Report number: ML12M23000982	
Name and Address of employer for whom the thorough examination was made: Morris Leslie, Errol Airfield, Errol, Perth, PH2 7TB			Address of premises at which the examination was made: Baston Creek, Salcombe TQ8 8DU		
Description and identification of the equipment: Equipment Type: JCB 540-140 Telehandler (SH21 YMW) ID: JCB5A8MGCM3060049 Quick Hitch Type: N/A Quick Hitch S/N: N/A		Safe Working Load(s): In Accordance with manufacture specification found in cab.	Date of manufacture if known: N/A	Date of last thorough examination: N/A	
Is this the first examination after installation or assembly at a new site or location?	YES		NO	X	
			Was the examination carried out:		
If the answer to the above question is YES has the equipment been installed correctly?	YES	X	NO		
			Within an interval of 6 months?		
		Within an interval of 12 months?		YES	X
		In accordance with an examination scheme?		YES	X
		After the occurrence of exceptional circumstances?		YES	X
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) None Found.					
Is the above an existing or imminent danger to persons *Note-This is a reportable defect				YES	X
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) N/A			YES by:		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: Equipment was found to be in safe working order at time of inspection.					
Particulars of any tests carried out as part of the examination: (If none state NONE) None					
Observations / additional comments relative to this thorough examination: Equipment was found to be in safe working order at time of inspection.					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	X
Name & Qualifications of person making this report: James Walsh City & Guilds, CITB		Name of person signing or authenticating this report on behalf of the author: Md James Walsh Signature:		Latest date by which next thorough examination must be carried out: 15/05/2024	
Name and address of employer of persons making and authenticating this report: Walsh Plant Ltd, Unit 3 Birchwood Industrial Estate, Hoe Lane, Nazeing, EN9 2RJ					