

Morris Leslie

PLANT SALES

Morris Leslie Excavator Inspection Form

ALL BOXES MUST BE COMPLETE FOR ALL MACHINES

MACHINE DETAILS			
Internal stock No:	HHC3817		
Manufacturer:	DOOSAN		
Model:	DX85R		
Year:	2022		
Hours:	1259		
Serial Number:	6003817		
Registration Number:	N/A		
Machine Start Code:	1745		
Condition:	<input checked="" type="checkbox"/> Used	<input type="checkbox"/> Ex Demo	
Location Name & Postcode:	BEDFORD 803 MK45 2FN		
ENGINE			
Engine Manufacturer:	N/A		
Engine Model:	N/A		
Engine Serial Number:	N/A		
Engine Output:	44.3 KW		
Emission Level:	<input type="checkbox"/> Stage IIIB / Tier IV interim	<input type="checkbox"/> Stage IV / Tier IV final	<input type="checkbox"/> Stage V / Tier IV final
Eco Mode:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
OTHER INFORMATION			
Gross Weight:	8600 KG		
CE Marked:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Cabin Type:	<input type="checkbox"/> Open Cabin	<input checked="" type="checkbox"/> Enclosed Cabin	
Operator Controls:	<input type="checkbox"/> Lever	<input checked="" type="checkbox"/> Joystick	
Air conditioning:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Heater:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Heated Seat:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
AD blue:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Attachments:	5X BUCKETS		
Quick Hitch:	<input checked="" type="checkbox"/> Hydraulic	<input type="checkbox"/> Manual	
Arm Length:	N/A		
Reach Type:	<input checked="" type="checkbox"/> Standard	<input type="checkbox"/> Long	
Tail Swing Configuration:	<input type="checkbox"/> Zero	<input type="checkbox"/> Reduced	<input type="checkbox"/> Conventional
Boom Type:	<input type="checkbox"/> 1-Piece	<input checked="" type="checkbox"/> 2-Piece	
Auxiliary Hydraulics:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Telematics:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Camera:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Rotating beacon:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Green beacon:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Paintwork:	GOOD		
CHASSIS			
Long Undercarriage:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Track Type:	<input checked="" type="checkbox"/> Rubber	<input type="checkbox"/> Steel	

Track % Remaining:	NS 80%	OS 80%	
Track Shoe Width:	N/A		
Bolt-On Pads:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Undercarriage Type:	<input checked="" type="checkbox"/> Fixed	<input type="checkbox"/> Variable	
Undercarriage % Remaining:	100%		
EXTERIOR			
Cab Guards:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Exterior Lighting:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
SELLER'S CONDITION REPORT			
Latest inspection:	27.02.2024		Shipping Length:
Condition Info:	GOOD		Shipping Width:
Full service history:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Shipping Height:
Certificates:	<input type="checkbox"/> CE Cert	<input type="checkbox"/> Loler Cert	Shipping Weight:
Inspected by:	ADRIAN MAER		
Date:	27.02.2024		

Please complete and email to: sales.info@morrisleslie.co.uk

