

Morris Leslie

PLANT SALES

Morris Leslie Telehandler Inspection Form

ALL BOXES MUST BE COMPLETE FOR ALL MACHINES

MACHINE DETAILS			
Internal stock No:	MLP13898		
Manufacturer:	JCB		
Model:	535-125		
Year:	2021		
Hours:	3147		
Serial Number:	3061992		
Registration Number:	SC21 WBG		
Machine Start Code:	1945		
Condition:	<input checked="" type="checkbox"/> Used	<input type="checkbox"/> Ex Demo	
Location Name & Postcode:	W'HALL WV12 4LF		
ENGINE			
Engine Manufacturer:	JCB		
Engine Model:	430 TA5-55		
Engine Serial Number:	U1852321		
Engine Output:	55	KW	
Emission Level:	<input type="checkbox"/> Stage IIIB / Tier IV interim	<input checked="" type="checkbox"/> Stage IV / Tier IV final	<input type="checkbox"/> Stage V / Tier IV final <input type="checkbox"/> Stage V / Tier V
POWERTRAIN			
DRIVE	<input type="checkbox"/> 2WD	<input checked="" type="checkbox"/> 4WD	
Transmission Type	<input type="checkbox"/> Hydrostatic	<input checked="" type="checkbox"/> Synchro	<input type="checkbox"/> Powershift
Number of speeds	4		
OTHER INFORMATION			
Gross Weight:	10020	KG	
CE Marked:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Country of Manufacture:	UK		
Cabin Type:	<input type="checkbox"/> Open Cabin	<input checked="" type="checkbox"/> Enclosed Cabin	
Operator Controls:	<input checked="" type="checkbox"/> Lever	<input type="checkbox"/> Joystick	
Air conditioning:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Heater:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
AD blue:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Additional hydraulics:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Road Lights:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Camera:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Rotating beacon:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Green beacon:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Paintwork:	OK		
CATEGORY SPECIFIC			
Capacity:	3500	KG	
Outriggers:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Max Forward Reach:	8	M	
Carriage Type:	<input type="checkbox"/> Standard	<input checked="" type="checkbox"/> Fork-Positioner	
Telematics:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Maximum Lift Height:	12	M	
Frame Leveling/Sway:	<input type="checkbox"/> Fixed	<input checked="" type="checkbox"/> Variable	
CHASSIS			
Towing Hitch:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Tyre % Remaining:	<input type="checkbox"/> N/S/F: 40	<input type="checkbox"/> O/S/F: 40	<input type="checkbox"/> N/S/R: 60 <input type="checkbox"/> O/S/R: 40
All-Wheel Steer:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
EXTERIOR			
ROPS:	<input checked="" type="checkbox"/> Enclosed	<input type="checkbox"/> Open	
Fenders:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Number of Fenders:	<input type="checkbox"/> 2	<input type="checkbox"/> 4	
SELLER'S CONDITION REPORT			
Latest inspection:	03.06.24	Shipping Length:	5840
Condition Info:	OK	Shipping Width:	2350
Full service history:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Shipping Height:	2590
Certificates:	<input checked="" type="checkbox"/> CE Cert <input checked="" type="checkbox"/> Loler Cert	Shipping Weight:	10020
Inspected by:	J.DENNING		
Date:	03.06.24		

Please complete and email to: sales.info@morrisleslie.co.uk

Morris Leslie

PLANT HIRE

5109024030

SERVICE REPORT

(Use for On-Site Service, Breakdowns, Damage and Repairs)

DEPOT No. 510

SR 72053

Customer Information			Site Address		
Address			Redrow Homes BRIZEN PARK 2C SHURDINGTON		
POST CODE	Inv. No.		POST CODE	Contact:-	
Acc. No.			6L53	CAR	
Date Reported	Time	Type of Equipment	Plant I/D No.	Contract No.	Chargeable?
		12m TELE	13898		NO
TYPE>	On Site Service	<input checked="" type="checkbox"/> Breakdown		Repair / Dam	Other

Reported Fault

.....

.....

.....

.....

Reported to:- Passed to:- Time:-

Engineers Report and Work carried out:-

ENGINE SERVICE @ 2847
NEXT SERVICE @ 3347.
CHANGE ENGINE OIL AND ALL FILTERS IN KIT.
BLEED FUEL SYSTEM AND RUN UP.
CHECKOIL LEVEL ALL GOOD

NOTE WILL NOT BE ABLE OIL CHANGE.

Parts				
Parts Used Description	Qty	Product Code	Price Each	Total
Travel Time	Labour Time		Sub Total	
			VAT	
			TOTAL	£

Customers Comments:-	Engineers/Fitters Signature
Customers Authorised Signatory <u>RP</u>	DATE:- 31/5/23
NAME (Block Caps)	NAME:- ATEDD
	w/s Sup

Morris Leslie

PLANT HIRE

SERVICE REPORT

(Use for On-Site Service, Breakdowns, Damage and Repairs)

S109021392

DEPOT No.

B-HAM

SR

70405

Customer Information

Address

REDROW HOMES

Site Address

BRIZEN PARK
SHARDINGTON

POST CODE

Acc. No.

Inv. No.

POST CODE

Contact:-

GLS3

Date Reported	Time	Type of Equipment	Plant I/D No.	Contract No.	Chargeable?
16-9-22		JCB 12.5m	13898		NO
TYPE>	On Site Service	<input checked="" type="checkbox"/> Breakdown		Repair / Dam	Other

Reported Fault

1701 Hrs

SITE SERVICE

NEXT SERVICE 2200 HRS

Reported to:-

Passed to:-

Time:-

Engineers Report and Work carried out:-

ALL FITTERS CHANGED - M/C GREASES FULLY -
FRONT AXLE OIL CHANGED, HAND BRAKE ADJ
SERVICE LIGHT RE-SET - STICKERS UP DATE ETC.

Parts

Parts Used Description	Qty	Product Code	Price Each	Total
1x JCB SERVICE KIT				
8x GALL OIL				
PARTS REQ 1x CAB FITTER (NOT IN KIT?)				
Travel Time 2 1/4	Labour Time 3 1/2	1x REAR NO-PLATE	Sub Total	
		1x " " LIGHT	VAT	
			TOTAL	£

Customers Comments:-

[Handwritten signature]

Customers Authorised

Signatory

NAME (Block Caps)

Engineers/Fitters Signature

DATE:-

NAME:-

w/s Sup

16-9-22
[Handwritten signature]

Morris Leslie

PLANT HIRE

5109018689

SERVICE REPORT

(Use for On-Site Service, Breakdowns, Damage and Repairs)

DEPOT No. **510**

SR **72765**

Customer Information				Site Address		
Address				REDROW HOMES. BRIZEN PARK 2C SHURDINGTON		
POST CODE		Inv. No.		POST CODE GL53 0AF		
Acc. No.				Contact:-		
Date Reported	Time	Type of Equipment	Plant I/D No.	Contract No.	Chargeable?	
		12M TELE	13898		NO	
TYPE>	On Site Service	<input checked="" type="checkbox"/> Breakdown		Repair / Dam	Other	

Reported Fault

FAULT CODE:
P0524-FF oil pressure

Reported to:- Passed to:- Time:-

Engineers Report and Work carried out:-

ENGINE SERVICE
 CHANGE ENGINE OIL, OIL FILTER BOTH FUEL FILTER.
 TRANS FILTER, HYDRO FILTER BOTH CAB FILTER
 BLEED FUEL SYSTEM START UP RECHECK.
 ENGINE OIL ALL OK.
 NOTE FAULT CODES ON DASH.
 P0524-FF OIL PRESSURE SWITCH.
 U1906-99.

Parts TRANS OIL PRESSURE LIGHT ON DASH.

Parts Used Description	Qty	Product Code	Price Each	Total
NEED JOB TO ATTEND FAULTS.				
SERVICE @ 653				
MS @ 1153				

Travel Time 1	Labour Time 2 1/2	Sub Total	
		VAT	
		TOTAL	£

Customers Comments:- RP - R PRINCE	Engineers/Fitters Signature <i>[Signature]</i> DATE:- 17/12/22 NAME:- A TEDD w/s Sup
Customers Authorised Signatory NAME (Block Caps)	



Development Member



GA1 Fleet Number:

MLP13898

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 and Power Regulations 1998

Date of Thorough Examination: 30/06/2023		Date of Report: 30/06/2023		Report number: ML12M23001365	
Name and Address of employer for whom the thorough examination was made: Morris Leslie, Errol Airfield, Errol, Perth, PH2 7TB			Address of premises at which the examination was made: Redrow South West Division, Redrow Homes Ltd, Brizen Park 2C, Farm Lane, Shurdington. GL53 0AF		
Description and identification of the equipment: Equipment Type: JCB 535-125 Telehandler (SC21 WBG) ID: JCB5ANMGCM3061992 Quick Hitch Type: N/A Quick Hitch S/N: N/A		Safe Working Load(s): In Accordance with manufacture specification found in cab.	Date of manufacture if known: N/A	Date of last thorough examination: N/A	
Is this the first examination after installation or assembly at a new site or location?		Was the examination carried out:			
YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Within an interval of 6 months?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
		Within an interval of 12 months?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		In accordance with an examination scheme?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		After the occurrence of exceptional circumstances?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) None Found.					
Is the above an existing or imminent danger to persons *Note-This is a reportable defect			YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) N/A			YES by:		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: Equipment was found to be in safe working order at time of inspection.					
Particulars of any tests carried out as part of the examination: (If none state NONE) None					
Observations / additional comments relative to this thorough examination: Equipment was found to be in safe working order at time of inspection.					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input type="checkbox"/> X <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name & Qualifications of person making this report: James Walsh City & Guilds, CITB		Name of person signing or authenticating this report on behalf of the author: <i>Mr James Walsh</i> Signature:		Latest date by which next thorough examination must be carried out: 29/06/2024	
Name and address of employer of persons making and authenticating this report: Walsh Plant Ltd, Unit 3 Birchwood Industrial Estate, Hoe Lane, Nazeing, EN9 2RJ					



DECLARATION OF CONFORMITY

NAME AND ADDRESS OF MANUFACTURER

JC BAMFORD EXCAVATORS LIMITED
LAKESIDE WORKS
ROCESTER
UTTOXETER
STAFFORDSHIRE
UNITED KINGDOM

HEREBY DECLARES THAT THE MACHINERY / EQUIPMENT DESCRIBED
BELOW COMPLIES WITH ALL UK AND EU RULES APPLICABLE

ST14 5JP
LIFT TRUCK, COMBUSTION-ENGINE DRIVEN, COUNTERBALANCED
(ROUGH TERRAIN TRUCKS)

DESCRIPTION OF MACHINERY / EQUIPMENT:

TRADE NAME:

JCB

MODEL NAME:

535V125

SERIAL NUMBER OF MACHINERY / EQUIPMENT:

JCB5ANMGCM3061992

COMPLIES WITH THE PROVISIONS OF THE "MACHINERY DIRECTIVE" (DIRECTIVE 2006/42/EC AS AMENDED)
AND THE SUPPLY OF MACHINE (SAFETY) REGULATIONS 2008 (AS AMENDED)

THE FOLLOWING STANDARDS HAVE BEEN USED:

BS EN 1459-1:2017+A1:2020

NAME AND ADDRESS OF THE PERSON ESTABLISHED IN THE EU
AUTHORISED TO COMPILE THE TECHNICAL CONSTRUCTION FILE
FOR UK REFER TO ADDRESS ABOVE AND SIGNATORY

Managing Director
JCB Vibromax GMBH
EUROPAALLEE 113a
50226 FRECHEN
GERMANY

COMPLIES WITH THE PROVISIONS OF THE "ELECTRO-MAGNETIC COMPATIBILITY DIRECTIVE" (DIRECTIVE 2014/30/EU AS AMENDED).
ELECTROMAGNETIC COMPATIBILITY REGULATIONS 2016 AS AMENDED

COMPLIES WITH THE PROVISIONS OF THE "NOISE EMISSIONS IN THE ENVIRONMENT BY EQUIPMENT FOR USE OUTDOORS DIRECTIVE" (DIRECTIVE 2000/14/EC
AS AMENDED) AND THE NOISE EMISSION IN THE ENVIRONMENT BY EQUIPMENT FOR USE OUTDOORS REGULATIONS 2001 [UK] (AS AMENDED)

NAME AND ADDRESS OF THE PERSON WHO KEEPS THE TECHNICAL
DOCUMENTATION:

PRINCIPAL ENGINEER NVH
J.C. BAMFORD EXCAVATORS LIMITED
LAKESIDE WORKS
ROCESTER
STAFFORDSHIRE
UNITED KINGDOM
ST14 5JP

CONFORMITY ASSESSMENT PROCEDURE:

ANNEX VI - PROCEDURE 1

NAME AND ADDRESS OF NOTIFIED BODY:

VINCOTTE NV/SA - NB 0026
B-1800 VILVOORDE, BELGIUM

AnP LTD - BN 8500
MANCHESTER, M14 4PN

MEASURED SOUND POWER LEVEL ON EQUIPMENT
REPRESENTATIVE FOR THIS TYPE:
GUARANTEED SOUND POWER LEVEL FOR THIS
EQUIPMENT:
NET INSTALLED POWER / MASS OF APPLIANCE:

103 dBA

104 dBA

55.0 kw

PLACE OF DECLARATION:

ROCESTER

DATE OF DECLARATION:

20/08/2021

NAME OF AUTHORISED SIGNATORY:

RICHARD BROOKS

POSITION:

ENGINEERING DIRECTOR

SIGNATURE:

UK

UK