

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	3K72057	Machine Start Code:	CODED KEY
Make:	KUBOTA	Model:			KX080
Fleet Number:	MLP13031	Registration Number:			N/A
Hour Clock Working:	YES	Machine Hours:			1530
Tyre Size:	N/A	N/S/F%:		N/S/R%:	O/S/R%:
Tracks (Steel/Rubber)	RUBBER	N/S % -	60%	O/S % -	60%
Blade:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Track Width:			N/A
Buckets:	YES	Bucket Sizes:			DITCH / 12" / 32"
Roller Drum Width:		Roller -Water Sprinklers System			
Skip (Straight/Swivel/Hi-Tip):		Transmission (Hydrostatic/Gear):			N/A
AdBlue:	NO	4th Gear:			N/A
Pallet Forks	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Fork Positioners	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Stabilisers:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Gross Weight(kg):	8425	Lift Capacity (kg):	N/A	Lift Height (m):	N/A
Engine (kw/hp) :	46.5	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Air Conditioning:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Controls (Lever/Joystick):	JOYSTICKS	Condition of Cab & Dash Decals			GOOD
Hitch (Manual/Hydraulic):	HYDRAULIC	Reversing Camera	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Body Work Condition (Any Damage):					GOOD
Glass (Any Damage):	GOOD	Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Road Lights:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Paintwork:					GOOD
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Date & Hours of Last Service:	12.09.2023 @ 1530 HR	Date Next Service Due:			2030 HR
Last Service Sheet Attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BEEN SENT					
Service Records Supplied:		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Red Key with Machine with picture:		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Manufacturers Decals with Machine:		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Depot:			803		
Inspected By:	ADRIAN MAER	Date:			15.09.2023