

# Morris Leslie

PLANT SALES

## Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

|   |   |                      |   |   |   |
|---|---|----------------------|---|---|---|
| Year:   | 2021  | Serial Number:       | 3009071   | Machine Start Code:   | 1945  |
| Make:   | JCB   | Model:               | 540-170   |   |   |
| Fleet Number:   | MLP12856  | Registration Number: | SG21 GDF  |   |   |
| Hour Clock Working:   | YES   | Machine Hours:       | 1276  |   |   |
| Tyre Size:  | 15.5/25   | N/S/F%:              | 40%   | O/S/F%:   | 60%   |
|   |   | N/S/R%:              | 50%   | O/S/R%:   | 40%   |
| Tracks (Steel/Rubber)   | N/S % -   |                      | O/S % -   |   |   |
| Blade:  | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | Track Width:         |   |   |   |
| Buckets:  | Bucket Sizes:   |                      |   |   |   |
| Roller Drum Width:  | Roller -Water Sprinklers System                                     |                      |   |   |   |
| Skip (Straight/Swivel/Hi-Tip):  | Transmission (Hydrostatic/Gear):                                    |                      | GEAR  |   |   |
| AdBlue:   | 4th Gear:   |                      | YES   |   |   |
| Pallet Forks  | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | Fork Positioners     | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | Stabilisers:  | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| Gross Weight(kg):   | 12300   | Lift Capacity (kg):  | 4000  | Lift Height (m):  | 17  |
| Engine (kw/hp) :  | 55  | Turbo:               | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | Air Conditioning:   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| Controls (Lever/Joystick):  | JOYSTICK  |                      | Condition of Cab & Dash Decals                                      | GOOD  |   |
| Hitch (Manual/Hydraulic):   | Reversing Camera  |                      | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |   |   |
| Body Work Condition (Any Damage):                                     | GOOD  |                      |   |   |   |
| Glass (Any Damage):   | GOOD  |                      | Mirrors:  | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |   |
| Road Lights:  | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |                      |   |   |   |
| Paintwork:  | GOOD  |                      |   |   |   |
| Auxiliary Pipe Work:  | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |                      |   |   |   |
| Double Acting:  | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |                      |   |   |   |
| Any other Comments OR Notes on the Condition:                         |   |                      |   |   |   |
| Amber Beacon:   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |                      | Green Seat Belt Beacon:   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |   |
| Date & Hours of Last Service:   | 1275 HR   |                      | Date Next Service Due:  | 1775 HR   |   |
| Last Service Sheet Attached:  | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |                      | Current Loler attached:   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |   |
| <b>*THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT*</b> |   |                      |   |   |   |
| Service Records Supplied:   | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |                      |   |   |   |
| Red Key with Machine with picture:                                    | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |                      |   |   |   |
| Manufacturers Decals with Machine:                                    | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |                      |   |   |   |
| Depot:  | 803   |                      |   |   |   |
| Inspected By:   | ADRIAN MAER   | Date:                | 05.09.2023  |   |   |