

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	3011494	Machine Start Code:	1945
Make:	JCB	Model:	540-170		
Fleet Number:	MLP13432	Registration Number:	SD21 KHE		
Hour Clock Working:	Y	Machine Hours:	1513		
Tyre Size:	15.5.25	N/S/F%:	60	O/S/F%:	60
		N/S/R%:	60	O/S/R%:	60
Tracks (Steel/Rubber)	N/A	N/S % -		O/S % -	
Blade:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Track Width:	N/A		
Buckets:	N/A	Bucket Sizes:	N/A		
Roller Drum Width:	N/A	Roller -Water Sprinklers System	N/A		
Skip (Straight/Swivel/Hi-Tip):	N/A	Transmission (Hydrostatic/Gear):	N/A		
AdBlue:	N/A	4th Gear:	Y		
Pallet Forks	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Fork Positioners	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Stabilisers:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Gross Weight(kg):	12300	Lift Capacity (kg):	4000	Lift Height (m):	17
Engine (kw/hp) :	55	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Air Conditioning:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Controls (Lever/Joystick):	JOY	Condition of Cab & Dash Decals	OK		
Hitch (Manual/Hydraulic):	N/A	Reversing Camera	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Body Work Condition					
(Any Damage):					
Glass (Any Damage):	NO	Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Road Lights:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Paintwork:	OK				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR					
Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Date & Hours of Last Service:	1509HRS 17.08.23	Date Next Service Due:	2009HRS		
Last Service Sheet Attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT					
Service Records Supplied:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Red Key with Machine with picture:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Depot:	810				
Inspected By:	J.DENNING	Date:	25.08.23		