

# Morris Leslie

PLANT SALES

## Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	TM3B10775	Machine Start Code:	CODED KEY
Make:	KUBOTA	Model:	U50-5		
Fleet Number:	MLP13844	Registration Number:	N/A		
Hour Clock Working:	YES	Machine Hours:	1147		
Tyre Size:	N/A	N/S/F%:		N/S/R%:	O/S/R%:
Tracks (Steel/Rubber)	RUBBER		N/S % -	60%	O/S % -
Blade:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Track Width:	N/A		
Buckets:	YES		Bucket Sizes:	DITCH / 12" / 36"	
Roller Drum Width:		Roller -Water Sprinklers System			
Skip (Straight/Swivel/Hi-Tip):		Transmission (Hydrostatic/Gear):	N/A		
AdBlue:	NO		4th Gear:	N/A	
Pallet Forks	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Fork Positioners	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Stabilisers:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Gross Weight(kg):	4965	Lift Capacity (kg):	N/A		Lift Height (m):
Engine (kw/hp) :	23.7	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Air Conditioning:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Controls (Lever/Joystick):	JOYSTICKS		Condition of Cab & Dash Decals	GOOD	
Hitch (Manual/Hydraulic):	HYDRAULIC		Reversing Camera	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Body Work Condition (Any Damage):	GOOD				
Glass (Any Damage):	GOOD		Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Road Lights:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Paintwork:	GOOD				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:					
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Date & Hours of Last Service:	24.08.23 @ 1147 HR		Date Next Service Due:	1647 HR	
Last Service Sheet Attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
<b>*THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT*</b>					
Service Records Supplied:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Red Key with Machine with picture:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Depot:	803				
Inspected By:	ADRIAN MAER	Date:	05.09.2023		