

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	71850	Machine Start Code:	n/a
Make:	Kubota	Model:	KX080-4		
Fleet Number:	MLP13026	Registration Number:	n/a		
Hour Clock Working:	yes	Machine Hours:	1531		
Tyre Size:	n/a	N/S/F%:	n/a	N/S/F%:	n/a
Tracks (Steel/Rubber)	Rubber	O/S/F%:	n/a	O/S/R%:	n/a
Blade:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	N/S % -	30%	O/S % -	30%
Buckets:	yes	Track Width:	450		
Roller Drum Width:	n/a	Bucket Sizes:	12'36' Ditch		
Skip (Straight/Swivel/Hi-Tip):	n/a	Roller -Water Sprinklers System	n/a		
AdBlue:	n/a	Transmission (Hydrostatic/Gear):	n/a		
Pallet Forks	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	4th Gear:	n/a		
Gross Weight(kg):	8315	Fork Positioners	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Stabilisers:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Engine (kw/hp) :	46.5 kw	Lift Capacity (kg):	n/a	Lift Height (m):	n/a
Controls (Lever/Joystick):	Levers & joysticks	Turbo:	<input type="checkbox"/> YES <input type="checkbox"/> NO	Air Conditioning:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Hitch (Manual/Hydraulic):	n/a	Condition of Cab & Dash Decals	OK		
Body Work Condition (Any Damage):	OK for age & Hours				
Glass (Any Damage):	n/a	Reversing Camera	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Mirrors:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Road Lights:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Paintwork:	OK for age & Hours		
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Any other Comments OR Notes on the Condition:			
Double Acting:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Last Service Sheet Attached:	<input type="checkbox"/> YES <input type="checkbox"/> NO	Date & Hours of Last Service:			
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BEEN SENT					
Service Records Supplied:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Date Next Service Due:			
Red Key with Machine with picture:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Last Service Sheet Attached:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Current Loler attached:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Manufacturers Decals with Machine:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Depot:	805		
Inspected By:	Robin Butler	Date:	11/08/2023		