

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

| | | | | | |
|--|---|----------------------------------|---|---------------------|--|
| Year: | 2021 | Serial Number: | 30278 | Machine Start Code: | n/a |
| Make: | KOBELCO | Model: | SK130-11S | | |
| Fleet Number: | SEL29558 | Registration Number: | | | |
| Hour Clock Working: | YES | Machine Hours: | 1436 | | |
| Tyre Size: | | N/S/F%: | | N/S/R%: | O/S/R%: |
| Tracks (Steel/Rubber) | STEEL | N/S % - | | O/S % - | |
| Blade: | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | Track Width: | | | |
| Buckets: | 3 | Bucket Sizes: | DITCH - 3FT - 4FT | | |
| Roller Drum Width: | | Roller -Water Sprinklers System | | | |
| Skip (Straight/Swivel/Hi-Tip): | | Transmission (Hydrostatic/Gear): | | | |
| AdBlue: | YES | 4th Gear: | | | |
| Pallet Forks | <input type="checkbox"/> YES <input type="checkbox"/> NO | Fork Positioners | <input type="checkbox"/> YES <input type="checkbox"/> NO | Stabilisers: | <input type="checkbox"/> YES <input type="checkbox"/> NO |
| Gross Weight(kg): | 15200 | Lift Capacity (kg): | | Lift Height (m): | |
| Engine (kw/hp) : | 86 | Turbo: | <input type="checkbox"/> YES <input type="checkbox"/> NO | Air Conditioning: | <input type="checkbox"/> YES <input type="checkbox"/> NO |
| Controls (Lever/Joystick): | LEVER & JOYSTICK | Condition of Cab & Dash Decals | GOOD | | |
| Hitch (Manual/Hydraulic): | HYDRAULIC | Reversing Camera | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | |
| Body Work Condition (Any Damage): | GENERAL WEAR & TEAR - REAR O/S PANEL DAMAGED | | | | |
| Glass (Any Damage): | | Mirrors: | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | |
| Road Lights: | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | | | |
| Paintwork: | GENERAL WEAR & TEAR | | | | |
| Auxiliary Pipe Work: | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | | | |
| Double Acting: | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | | | |
| Any other Comments OR Notes on the Condition: | | | | | |
| Amber Beacon: | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | Green Seat Belt Beacon: | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | | |
| Date & Hours of Last Service: | UNKNOWN | Date Next Service Due: | | | |
| Last Service Sheet Attached: | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | Current Loler attached: | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | |
| *THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT* | | | | | |
| Service Records Supplied: | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | | | | |
| Red Key with Machine with picture: | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | | | | |
| Manufacturers Decals with Machine: | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | | | |
| Depot: | | | | | |
| Inspected By: | | Date: | | | |